



ATLAS FXR

Thunderbolt™ and USB CFexpress Card Reader



INCLUDES

- OWC Atlas FXR
- Thunderbolt 3 cable with tethered USB Type-A adapter

SYSTEM REQUIREMENTS

Works with any Mac, PC, Chromebook, iPad, or Android device with a USB (Type-A or Type-C) or Thunderbolt (USB-C) port

- macOS 11.1 or later for Thunderbolt hosts
- macOS 10.14.6 or later for USB hosts
- Windows 10 or later
- Linux
- Chrome OS
- iPadOS 13 or later
- Android 11 or later

Supported Media:

- (1) CFexpress Type B

INSTALLATION INFORMATION

The Web Manual can be viewed by visiting go.owc.com/atlasfxr/manual

Or scanning QR code



TECHNICAL SUPPORT



Phone: M–F, 8am–6pm CT
1.866.692.7100 (N. America)
+1.815.338.4751 (Int'l)



Chat: M–F, 8am–6pm,
Sat. 9am–5pm CT
www.owc.com/support



Email: Answered
within 48 hours
www.owc.com/support

QUICK START GUIDE

GETTING STARTED

DEVICE USAGE

OVERVIEW



1. Connect the included data cable into the USB 3.2 10Gb/s port on the OWC Atlas FXR.
2. Connect the OWC Atlas FXR to your desired system or device.
3. Insert a CFexpress Type B card into the card slot. Note: May take up to 30 seconds for the card to be recognized when using over iPadOS, Android, or Chrome OS.

- A. Enclosure LED:
Data Connection = Blue
- B. CFexpress Type B
- C. Thunderbolt 3
(USB 3.2 10Gb/s Port)